

**Secor's Collision Technology**  
**575 Broad Street**  
**New London, CT, 06320**

Phone: 860-442-3232 FAX: 860-447-8557  
 Website: secorauto.com Email: jshortell@secorauto.com

*Collision Damage Estimate*

Vehicle Owner: \_\_\_\_\_ Vehicle: 2001 Volvo V70 T-5  
 Name: William Tyler VIN: YV4G53DY42001999  
 Address: 155 Scott Hill, Lebanon, CT Phone: \_\_\_\_\_  
 06459-2705 Color: Silver  
 Phone # 1: 860-447-0511 Image: 24705  
 Phone # 2: \_\_\_\_\_ License: \_\_\_\_\_

CONFIDENTIAL

Line	Operation	Description	Part No.	Qty.	Price	Labor Hrs
1		REAR BUMPER				
2	Misc	O/H rear bumper				2.0
3	Replace	Bumper cover w/o V70R silver	9477527	1	547.95	
4	Replace	Impact bar	9190315	1	111.20	
5	Replace	Absorber	9190316	1	62.24	
6	Replace	Center molding	9190317	1	70.50	
7	Replace	LT Outer molding	9484232	1	27.44	
8	Replace	Support bar	30699145	1	311.80	3.5
9	Replace	RT Bracket	8648194	1	12.88	
10	Replace	Seal	9203080	1	24.63	
11		REAR BODY & FLOOR				
12	Repair	Opening frame (BOR)				7.5
13	Repair	Opening frame (BOR)				1.4
14	Refinish	Add for Clear Coat				.6
15	Replace	Rear body reinf (BOR)	30663356	1	182.27	4.5
16	Refinish	Rear body reinf (BOR)				1.0
17	Repair	Rear floor pan				4.0
18	Refinish	Rear floor pan				1.0
19	Refinish	Overlap Major Non-Adj. Panel				-2
20	Repair	Inner quarters (Weld Damage)				1.0
21	Refinish	Inner quarters (Weld Damage)				.5
22	Remove/Install	Interior trim				.5

Line	Operation	Description	Part No.	Qty.	Price	Labor Hrs
23	Misc	Cover/Protect interior from welding/over		1	5.00	.3
24		ELECTRICAL				
25	Remove/Install	Battery 600 amp				.3
26		WHEELS				
27	Remove/Install	Spare Wheel, spare w/o XC				.3
28		LIFT GATE				
29	Repair	Lift gate				6.0
30	Refinish	Lift gate				1.6
31	Refinish	Overlap Major Adj. Panel				-4
32	Refinish	Add for Clear Coat				.2
33	Replace	Nameplate "VOLVO"	9483065	1	26.67	.2
34	Replace	Nameplate "V70"	9483064	1	29.12	.2
35	Replace	Nameplate "T5"	9157135	1	29.12	.2
36	Remove/Install	Handle, outside				.4
37	Remove/Install	Lift gate trim upper beige				.2
38	Remove/Install	Lift gate trim lower beige				.4
39		REAR LAMPS				
40	Remove/Install	LT Tail lamp upper				
41	Remove/Install	RT Tail lamp upper				
42	Remove/Install	RT Tail lamp lower				.6
43	Remove/Install	LT Tail lamp lower				.6
44		QUARTER PANEL				
45	Repair	LT Quarter panel				3.0
46	Refinish	LT Quarter panel				2.4
47	Refinish	Overlap Major Adj. Panel				-4
48	Refinish	Add for Clear Coat				.4
49	Repair	RT Quarter panel (WELD DAMAGE)				1.0
50	Refinish	RT Quarter panel (WELD DAMAGE)				.5
51	Refinish	Overlap Major Adj. Panel				-4
52	Refinish	Add for Clear Coat				.1
53	Remove/Install	RT Air outlet vent				.2
54	Remove/Install	LT Air outlet vent				.2
55		PILLARS, ROCKER & FLOOR				
56	Remove/Install	RT Rocker molding front				.5
57	Remove/Install	LT Rocker molding front				.5

Line	Operation	Description	Part No.	Qty.	Price	Labor Hrs
58	Remove/Install	RT Rocker molding rear				.4
59	Remove/Install	LT Rocker molding rear				.4
60	Replace	RT Rocker molding clip / 3 @ 1.86 each	9484284	3	5.58	
61	Replace	LT Rocker molding clip / 3 @ 1.86 each	9484284	3	5.58	
62	Replace	RT Rocker molding rivet / 5 @ 0.49 each	9133417	5	2.45	
63	Replace	LT Rocker molding rivet / 5 @ 0.49 each	9133417	5	2.45	
64	Replace	Rivets / 10 @ 0.3 each		10	3.00	
65	Repair	Frame/Unibody Setup & Measure				2.0
66	Repair	Pull/align rear unibody				6.0
67		ROOF				
68	Remove/Install	LT Drip molding front silver				.2
69	Remove/Install	LT Drip molding center silver				.2
70	Remove/Install	LT Drip molding rear silver				.2
71	Remove/Install	LT End silver				
72	Remove/Install	LT Side rail w/o XC				.5
73	Blend	LT Outer roof rail				1.0
74		FRONT DOOR				
75	Remove/Install	LT Door w'strip				.5
76		REAR DOOR				
77	Remove/Install	LT Door w'strip				.5
78	Misc	Color Sand/buff & clean up		1	5.00	1.5
79	Replace	Caulking/ Seam Sealer		1	10.00	.3
80	Replace	Cover for overspray protection		1	5.00	.3
81	Replace	Restore corrosion protection		1	10.00	.5
82	Replace	Mask openings from overspray		1	5.00	.5
83	Replace	Weld Through Primer		1	5.00	.2
84	Replace	Mask/cover car for primer coat		1	5.00	.3
85	Misc	Hazardous waste disposal		1	3.00	

Line	Operation	Description	Part No.	Qty.	Price	Labor Hrs
<b>Totals:</b>						
	Body Labor:	44.6 Hrs @ \$60.00	Per Hr =	\$2,676.00	<b>Labor:</b>	2971.20
	Paint Labor:	9.3 Hrs @ \$60.00	Per Hr =	\$558.00	<b>Parts:</b>	1494.88
	Frame Labor:	8.0 Hrs @ \$60.00	Per Hr =	\$480.00	<b>Materials:</b>	271.00
					<b>Misc:</b>	1837.98
					<b>Taxes:</b>	285.00
		61.9 Hrs		\$3,714.00	<b>Grand Total:</b>	6860.06

This estimate is based on our inspection and does not cover additional parts or labor that may be required after the work has been started. Occasionally, worn or damaged parts are discovered that were not evident on the first inspection. Therefore, the above prices are not guaranteed. Parts prices subject to change due to manufacturer's price increases.

**BE SURE TO SHOW THIS ESTIMATE TO THE INSURANCE APPRAISER WHO INSPECTS YOUR VEHICLE.**

You have the right to have your vehicle repaired at the shop of your choice, and you do not have to get more than one estimate. If the insurance company tries to steer you to another shop, or tells you to get more than one estimate, please let us know immediately!

The insurance company can not require you to take your car to a drive-in claims center to have them look at it. You may arrange to meet the appraiser at our shop, or you can have the appraiser come to your home or work place.

#### SECOR'S COLLISION TECHNOLOGY INSURANCE COMPANY REFERRAL LIST

When choosing an insurance company, there are other things to consider beside premium costs. Saving a few dollars on your premium may cost you hundreds or thousands of dollars when it comes time to actually use your insurance. If your insurance company uses unfair practices, or refuses to pay the necessary costs to repair your vehicle properly, the premium savings become worthless.

Below is a list of insurance companies that we find fair, easy to work with, and treat their customers well. If an insurance company is not on our list it doesn't necessarily mean they are a bad company. It may mean that we haven't dealt with them enough to recommend them. And just because they make the list doesn't mean they are the perfect company. Personnel changes are constant, and it is the people who shape your experience with an insurance company.

Amica  
Chubb  
Geico  
Hartford  
Peerless  
State Farm  
Travelers  
USAA